


BRASS SCREW THREADING & TURNING MACHINE



Brass screw turning boring & Threading nachine with rack drive double slide and collet attavhment complete with one collet but without electricals - motor attachment, pulley & belt.

Model	BS-12	BS-19	BS-25	BS-38
Max. Collet cap.	1/2"	3/4"	1"	1-1/2"
Turning & Boring Cap.	1/16" to 7/16"	1/8" to 11/16"	0	0
Threading Cap.	0 to 12 BA	1/4 10 1/2"	0	0
Max. Length of Threading	3"	3.1/2"	4"	4"
H. P. required	2-Jan	1	1	2

Extra accessories Motor